Location: THRIFTWAY SUPER STOP 7 Sys Fac ID: 12-00101

2035 W PARK AVE Last Inspected On: 6/28/2013

ANACONDA, MT 59711 DEER LODGE Operating Permit Renewal Date: 11/13/2016

**Contact:** Daivd Sutey, (406) 494-2305

Owners/Operators: Sutey Oil Co Inc, Owner (406)-494-2305 2000 HOLMES AVE

BUTTE MT 59701-3553

Louie Sutey, UST Class A Operator Toni Clemons, UST Class B Operator Vickie Hall, UST Class B Operator Jack Hook, UST Class B Operator Allyn Moses, UST Class B Operator Jack Hook, UST Class B Global Operator Louie Sutey, UST Class B Global Operator

Tank ld	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
2	22	7/1/1993	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
2047			None	Double-Walled	Yes
Currently in Use		7/1/2003	Mechanical Line Leak Detector	Pressurized	Not Applicable
Diesel		8/29/2007	Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
12,000		9/10/2009			
3	22	7/1/1993	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
2046			None	Double-Walled	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Not Applicable
Gasoline		8/29/2007	Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
12,000		9/10/2009			
4	44	12/31/1971	Cathodically Protected Steel	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
2045			Lined Interior/Impressed Current	Double-Walled	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Impressed Current
Gasoline		7/11/2012	Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
10,000		9/10/2009			

Location: A & A TECHNICAL REPAIR INC Sys Fac ID: 12-01470

701 E PARK AVE Last Inspected On: 2/10/2016

ANACONDA, MT 59711 DEER LODGE Operating Permit Renewal Date:

Contact: John Atkerson, (406) 563-5779

Owners/Operators: John Atkerson, Owner (406)-494-5683 701 E PARK AVE ANACONDA MT 59711-2550

> John Atkerson, UST Class A Operator Lorna Atkerson, UST Class A Operator John Atkerson, UST Class B Global Operator Lorna Atkerson, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	21	5/1/1994	Fiberglass Reinforced Plastic	Flexible Plastic	Positive Shutoff
2096		7/20/2010	None	Double-Walled	Yes
Temporarily Out of Use			Continuous Interstitial Monitoring	Safe Suction	Not Applicable
Diesel			Automatic Tank Gauging 0.2	Continuous Interstitial Monitor, Deferred	
5,000					
7	21	5/1/1994	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
2095		7/20/2010	None	Double-Walled	Yes
Temporarily Out of Use			Continuous Interstitial Monitoring	Pressurized	Not Applicable
Gasoline			Automatic Tank Gauging 0.2	Continuous Interstitial Monitor	
5,000					
8	21	5/1/1994	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
2094		7/20/2010	None	Double-Walled	Yes
Temporarily Out of Use			Continuous Interstitial Monitoring	Pressurized	Not Applicable
Gasoline			Automatic Tank Gauging 0.2	Continuous Interstitial Monitor	
6,000					

Location: THRIFTWAY SUPER STOP 3 Sys Fac ID: 12-07938

1420 E PARK AVE Last Inspected On: 6/8/2013

ANACONDA, MT 59711 DEER LODGE Operating Permit Renewal Date: 6/12/2016

**Contact:** David Sutey, (406) 494-2305

Owners/Operators: Sutey Oil Co Inc, Owner (406)-494-2305 2000 HOLMES AVE BUTTE MT 59701-3553

Louie Sutey, UST Class A Operator
Jack Hook, UST Class B Operator
Ted Weinman, UST Class B Operator
Jack Hook, UST Class B Global Operator
Louie Sutey, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	25	9/1/1990	Fiberglass Reinforced Plastic	Flexible Plastic	Flapper Valve (Auto Shutoff)
2050		10/17/2012	None	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Gasoline			Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.2, Continuous Interstitial Monitor, MLLD Line Tightness Testing	
12,000					
2	25	9/1/1990	Fiberglass Reinforced Plastic	Flexible Plastic	Flapper Valve (Auto Shutoff)
2049		10/17/2012	None	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Gasoline			Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.2, Continuous Interstitial Monitor, MLLD Line Tightness Testing	
12,000					
4	25	9/1/1990	Fiberglass Reinforced Plastic	Flexible Plastic	Flapper Valve (Auto Shutoff)
2048		10/24/2012	None	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Gasoline			Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.2, Continuous Interstitial Monitor, MLLD Line Tightness Testing	
15,000					

Location: THRIFTWAY SUPER STOP 3 Sys Fac ID: 12-07938

1420 E PARK AVE Last Inspected On: 6/8/2013

ANACONDA, MT 59711 DEER LODGE Operating Permit Renewal Date: 6/12/2016

**Contact:** David Sutey, (406) 494-2305

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
9	25	9/1/1990	Fiberglass Reinforced Plastic	Flexible Plastic	Flapper Valve (Auto Shutoff)
2052		10/17/2012	None	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Diesel			Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.2, Continuous Interstitial Monitor, MLLD Line Tightness Testing	
6,000					
10	25	9/1/1990	Fiberglass Reinforced Plastic	Flexible Plastic	Flapper Valve (Auto Shutoff)
2051		10/17/2012	None	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Diesel			Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.2, Continuous Interstitial Monitor, MLLD Line Tightness Testing	
6,000					

Location: TOWN PUMP INC ANACONDA 2 Sys Fac ID: 12-08668

819 W PARK AVE Last Inspected On: 2/3/2015

ANACONDA, MT 59711 DEER LODGE Operating Permit Renewal Date: 2/6/2018

Contact: Kevin Kenneally, (406) 563-6707

**Owners/Operators:** Town Pump of Anaconda Inc, Owner (406)-497-6700 PO BOX 6000

BUTTE MT 59702-6000

Trent Biggers, UST Class A Operator
Trent Biggers, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	24	4/1/1991	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
2410			None	None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Diesel			Stat. Inventory Reconcilitation, Approved Remote Monitoring	Stat. Inventory Reconcilitation, Approved Remote Monitoring	
10,000		10/31/2006	TLS-350/Gilbarco EMC , Veeder Root		
2	24	4/1/1991	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
2409			None	None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Gasoline			Stat. Inventory Reconcilitation, Approved Remote Monitoring	Stat. Inventory Reconcilitation, Approved Remote Monitoring	
12,000		10/31/2006	TLS-350/Gilbarco EMC , Veeder Root		
5	24	4/1/1991	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
2407			None	None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Gasoline			Stat. Inventory Reconcilitation, Approved Remote Monitoring	Stat. Inventory Reconcilitation, Approved Remote Monitoring	
12,000		10/31/2006	TLS-350/Gilbarco EMC , Veeder Root		
6	24	4/1/1991	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Ball Float Valve
2408			None	None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Gasoline			Stat. Inventory Reconcilitation, Approved Remote Monitoring	Stat. Inventory Reconcilitation, Approved Remote Monitoring	
12,000		10/31/2006	TLS-350/Gilbarco EMC , Veeder Root		

TOWN PUMP INC ANACONDA 1 Location: **Sys Fac ID:** 12-09326

6940 MT HWY 1 SUITE A Last Inspected On: 2/2/2015

ANACONDA, MT 59711 **DEER LODGE Operating Permit Renewal Date:** 5/31/2018

(406)-497-6947 PO BOX 6000

Trent Biggers, (406) 497-6700

BUTTE MT 59702-2534

Trent Biggers, UST Class A Operator Daniel Sampson, UST Class A Operator Trent Biggers, UST Class B Global Operator Daniel Sampson, UST Class B Global Operator

Contact:

Owners/Operators: Town Pump Inc, Owner

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	21	11/1/1994	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
2414			None	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Gasoline		6/24/2014	Stat. Inventory Reconcilitation, Approved Remote Monitoring	Stat. Inventory Reconcilitation, Approved Remote Monitoring	
12,000		9/1/2005	TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	
2	21	12/1/1994	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
2413			None	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Gasoline		6/24/2014	Stat. Inventory Reconcilitation, Approved Remote Monitoring	Stat. Inventory Reconcilitation, Approved Remote Monitoring	
10,000		9/1/2005	TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	
3	24	5/1/1991	Bare Steel	Fiberglass Reinforced Plastic	Ball Float Valve
2412			Impressed Current	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Gasoline		6/24/2014	Stat. Inventory Reconcilitation, Approved Remote Monitoring	Stat. Inventory Reconcilitation, Approved Remote Monitoring	
12,000		9/1/2005	TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	

Location: TOWN PUMP INC ANACONDA 1 Sys Fac ID: 12-09326

6940 MT HWY 1 SUITE A Last Inspected On: 2/2/2015

ANACONDA, MT 59711 DEER LODGE Operating Permit Renewal Date: 5/31/2018

**Contact:** Trent Biggers, (406) 497-6700

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
4	24	5/1/1991	Bare Steel	Flexible Plastic	Ball Float Valve
2411			Impressed Current	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Impressed Current
Diesel		6/24/2014	Stat. Inventory Reconcilitation, Approved Remote Monitoring	Stat. Inventory Reconcilitation, Approved Remote Monitoring	
12,000		9/1/2005	TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	
9	14	7/1/2001	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
4574			Double-Walled	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Diesel		5/5/2012	Continuous Interstitial Monitor, Stat. Inventory Reconcilitation, Approved Remote Monitoring	Stat. Inventory Reconcilitation, Approved Remote Monitoring	
10,000		9/1/2005	TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	
10	14	7/1/2001	Fiberglass Reinforced Plastic	Flexible Plastic	Ball Float Valve
4575			Double-Walled	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Diesel		5/5/2012	Continuous Interstitial Monitor, Stat. Inventory Reconcilitation, Approved Remote Monitoring	Stat. Inventory Reconcilitation, Approved Remote Monitoring	
5,000		9/1/2005	TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	

Location: MAIN GRANULATES SLAG PILE - ANACONDA SMELTER SITE Sys Fac ID: 12-10912

105 N SILVER ST Last Inspected On: 6/21/2013

ANACONDA, MT 59711 DEER LODGE Operating Permit Renewal Date: 9/8/2016

Contact: John Gentry, (406) 560-0375

(219)-864-0909 2105 NORTH WINDS DRIVE DYER IN 46311

DYER IN 40

John Gentry, UST Class A Operator Don Haney, UST Class A Operator

Owners/Operators: U.S. Minerals Inc, Owner/Operator

John Gentry, UST Class B Global Operator Timothy J Ledford, UST Class B Global Operator

	_				
Гank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP Tank Detection F	Primary Pipe Detection	Vapor Recovery	
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	30	4/16/1985	Bare Steel	Steel	
1836	Yes	2/19/2013	None	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Pressurized	Not Applicable
Diesel			Not Listed	Not Listed	
12,800		2/19/2013			

### Facility Summary in DEER LODGE County in the City of WARM SPRINGS

Location: XANTHOPOULOS BLDG Sys Fac ID: 12-07585

2 C ST Last Inspected On: 6/19/2014

WARM SPRINGS, MT 59756 DEER LODGE Operating Permit Renewal Date: 11/26/2017

**Contact:** Woody Casey, (406) 693-7110

Owners/Operators: Montana Dept of Corrections, Owner (406)-444-4931 MIKE FERRITER

PO BOX 201301

HELENA MT 59620-1301

Jerry Hancock, UST Class A Operator Jerry Hancock, UST Class B Operator

Tank ld	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity			Line Tightness	ATG Type	Secondary Pipe Detection
4	29	1/1/1987	Fiberglass Reinforced Plastic	Flexible Plastic	Flapper Valve (Auto Shutoff)
829		8/7/2015	None	Double-Walled	Yes
Currently in Use			Not Required	U.S. Suction	Not Applicable
Diesel			Automatic Tank Gauging 0.1	Continuous Interstitial Monitor	
2,000			TLS-300 , Veeder Root		